

Photo 1

---

GENERAL VIEW OF PROPERTY



Photo 2

---

GENERAL VIEW OF PROPERTY



Photo 3

---

GENERAL VIEW OF PROPERTY



Photo 4

---

GENERAL VIEW OF PROPERTY



Photo 5

---

GENERAL VIEW OF PROPERTY



Photo 6

---

GENERAL VIEW OF PARKING



Photo 7

---

GENERAL VIEW OF TYPICAL ROOF



Photo 8

---

GENERAL VIEW OF TYPICAL STAIRWAY



Photo 9

---

GENERAL VIEW OF TYPICAL ELEVATED WALKWAY



Photo 10

---

GENERAL VIEW OF GUARDRAILS



Photo 11

---

GENERAL VIEW OF ELECTRICAL EQUIPMENT




Photo 12

---

GENERAL VIEW OF ELEVATOR EQUIPMENT



Photo 13

---

GENERAL VIEW OF HVAC EQUIPMENT



Photo 14

---

GENERAL VIEW OF FIRE ALARM PANEL



Photo 15

---

GENERAL VIEW OF FIRE EXTINGUISHER



Photo 16

---

GENERAL VIEW OF BUILDING'S FINISH



Photo 17

---

GENERAL VIEW OF BUILDING'S FINISH



Photo 18

---

GENERAL VIEW OF BUILDING'S FINISH



Photo 19

GENERAL VIEW OF BUILDING'S FINISH



Photo 20

GENERAL VIEW OF BUILDING'S FINISH



Photo 21

GENERAL VIEW OF BUILDING'S FINISH



Photo 22

---

View of Stucco cracking at balcony beam.



Photo 23

---

View of Bulging/Cracking in Stucco of previously repaired area on elevated walkway.



Photo 24

---

View of Stucco cracking at the edge of balcony.



Photo 25

---

View of Bulging/Cracking in Stucco of previously repaired area on elevated walkway.



Photo 26

---


View of Bulging/Cracking in Stucco of previously repaired area on elevated walkway.



Photo 27

---

View of Cracking in concrete topping of elevated walkway.



444 Bouchelle Drive, New Smyrna Beach, Florida



General view of deflections in wood beams supporting balconies at the rear of the structure.